

Item: Arri Kit (Continuous tungsten lighting)

Includes:

1x 650 light + 1 barn door
1x 300 light + 1 barn door
1x 150 light + 1 barn door
2 heat thermal gloves
3x Arri light stands
1x Arri mount speeding
1x XS Chimera soft box

Note:

- Lights will become VERY hot while using
- Use gloves when touching light
- Give yourself an extra 30 minutes at the end of your shoot to let the lights cool down before putting away
- Do NOT attach paper/gels/anything flammable to close to the light. It will melt/ burn